




NOVA CHAIR ASSEMBLY GUIDE



Unpack components for easy access to parts.
Note: The 3 black screws are required for fastening the seat-back.



Place seat on flat surface, padded side facing down. Place spacers between seat and mechanism at the 2 front holes. Align seat mechanism as pictured. Fasten to the base of the seat cushion.
4 screws, 4 washers and 2 spacers required.



Slide seat-back mount into base mechanism mounting plate. Align the holes and fasten.
3 screws and 3 washers required.



Slide thin side of gas cannister into base mechanism.
No fasteners required.



Slide the completed base onto gas cannister.

Required installation tools:
Allen key (provided)
Large Phillips/star screwdriver